










FIG. 1

PDF Signature Capture - SIG2.SIG

File Edit View Communication Help


| | | | |
|---|---|--------------------------------|-----------------------|
| symbol | BANK OF SYMBOL One Symbol Plaza Holttsville, NY 11742 | CHECK NO. 101 DATE 05/07/96 | Clear Change Level |
| PAY TO THE ORDER OF Steven Chew | | 1000000 | Compression Level: |
| One Million only | | Dollars | |
| MEMO For Fun | | | Bytes |
| Signature After Decompression | | | |
|  | | Bytes | % |
| Ready | | NUM | |

FIG. 2




| | | |
|---|--|---|
|  | BANK OF SYMBOL One Symbol Plaza Holtsville, NY, 11742 | CHECK NO. 100 |
| | DATE <u>05/07/96</u> | |
| PAY TO THE ORDER OF <u>Sundeep Kumar</u> | | \$ 1000 |
| <u>One Thousand</u> | | DOLLARS |
|  | | |
| MEMO <u>For Fun</u> | |  |
| :017000625 7865 66 8879 ' | | |

FIG. 2 is a schematic diagram of the system of the present invention.




FIG. 3

FIG. 4

MIRS RECEIPT

Dear Mr. Jones:

Your Package Has Arrived!

Shipped By:

Symbol Technologies, Inc.
One Symbol Plaza
Holstville, NY 11742-1300

Contents:

5 Spectrum 24 11 Megabit Wireless LAN Cards

Package Location:

MIRS Central
One Ohio Road
Anywhere, OH 22222


Instructions:

1. Go to the MIRS Location
2. Sign in the space indicated
3. Allow the MIRS to scan your signature and the bar code
4. Retrieve your package

Scan Below

AND

Scan Below



Sign Here

DO NOT SIGN UNTIL YOU HAVE ARRIVED AT THE MIRS!

FIG. 4A

MIRS RECEIPT

Dear Mr. Jones:

Your Package Has Arrived!

Shipped By:

Symbol Technologies, Inc.
One Symbol Plaza
Holstville, NY 11742-1300

Contents:

5 Spectrum 24 11 Megabit Wireless LAN Cards

Package Location:

MIRS Central
One Ohio Road
Anywhere, OH 22222



Instructions:

1. Go to the MIRS Location
2. Sign in the space indicated
3. Allow the MIRS to scan your signature and the bar code
4. Retrieve your package

Scan Below

AND

Scan Below



Sign In The Space Above

DO NOT SIGN UNTIL YOU HAVE ARRIVED AT THE MIRS!